

**KOBELCO**

**USED EQUIPMENT CENTER**  
**Jl. Raya Kemang-Parung No. 168A, Kel,**  
**Kemang**  
**Kabupaten Bogor, Jawa Barat**

**PT.DAYA KOBELCO CMI**  
**Kawasan MM2100 Jl.Halmahera Blok**  
**DD-10**  
**Cikarang Barat**

**KOBELCO USED SK200-10**



**MODEL:** SK200-10 HD  
**CAPACITY:** 20 T (Year 2019)  
**S/NO:** YN15426052  
**ENGINE HRS:** 13.343  
**CONDITION:** As Is Condition  
**DELIVERY TERM:** Franco PT. DKCMI, USED EQUIPMENT CENTER, Bogor  
**PRICE:** Rp 799,000,000 (exclude Tax 11%)

**Used crawler crane condition**

**Inspection summary**

Part	Evaluation
LOWER MACHINE	4.0 ★★ ★★ ★★ ★★ ☆
OPERATOR CAB	4.0 ★★ ★★ ★★ ★★ ☆
PERFORMANCE	4.0 ★★ ★★ ★★ ★★ ☆
UPPER MACHINE	4.0 ★★ ★★ ★★ ★★ ☆
ATTACHMENT	4.0 ★★ ★★ ★★ ★★ ☆
<b>Total</b>	<b>4.0</b> ★★ ★★ ★★ ★★ ☆

**Judgement Criteria**

- ★★★★★ :Close to brand new or excellent condition.
- ★★★★ :Fair Workable condition under operating hrs./mileage serviced.
- ★★★ :Workable condition, but minor repair is required. / Small leakage.
- ★★ :Workable condition, but mager repair is required. / Middle leakage.
- ★ : Non -workable, missing part. / Big leakage.



**MODEL :** SK200-10  
**Y.O.M.:** 2019  
**S/N :** YN15426052

**Conclusion & Comments**

**Conclusion & Comments**

Unit Condition : New Tracklink & Sprocket, Re-sealing Clinder Boom, Arm, Bucket, Service 2000 HM, Overall, condition unit ready to work, the performance is in manufacture standard

**Conducted the machine rectification**

As Is Condition

~Remarks~

- This document reflects the condition of this Excavator at the time of inspection to the best of our ability.
- We will not be held accountable for any liabilities, from this machine condition report. ·Please contact us for the viewing and inspection arrangement of the machine.

Photos

