

USED EQUIPMENT CENTER

Kawasan Pergudangan Kamal Indah I Blok F No.89 Jl.Kamal Benda Raya Jakarta

PT.DAYA KOBELCO CMI

Kawasan MM2100 Jl.Halmahera Blok DD-10 Cikarang Barat

BULLETIN NO:

KOBELCO USED SK200-10



MODEL: Kobelco SK200-10 CAPACITY: 20 T (Year 2019) YN15426022 S/NO: **ENGINE HRS:** 12844

CONDITION: As Is Condition **DELIVERY TERM:** FOT KAMAL

PRICE: 875.000.000 (exclude Tax 11%) Rр

Used crawler crane condition

Inspection summary

Part		Evaluation					
LOWER MACHINE	2.0	A	A	S	W	W	
OPERATOR CAB	3.0	25	A	A	W	23	
PERPORMANCE	4.0	25	25	25	25	25	
UPPER MACHINE	4.5	4	X	A	A	W	
ATTACHMENT	2.0	A	A	23	23	23	
Total	3.0	A	A	A	2	W	

Judgement Criteria

:Close to brand new or excellent condition.

- **** :Fair Workable condition under operating hrs/mileage serviced.
- *** : Workable condition, but minor repair is required. / Small leakage. ** : Workable condition, but mager repair is required. / Middle leakage.
- ★ : Non -workable, missing part. / Big leakage.

MODEL: SK200-10 Y.O.M.: 2019 S/N: YN15426022

Conclusion & Comments

Conclusion & Comments

Overall, condition unit ready to work, the ferformace is in manufacture standard but must be repair for

Conducted the machine rectification

As Is Condition

[~]Remarks~

[·]This document reflects the condition of this Excavator at the time of inspection to the best of our ability.

[·] We will not be held accountable for any liabilities, from this machine condition report. • Please contact us for the viewing and inspection arrangement of

<u>Photos</u>























