

**KOBELCO**

**USED EQUIPMENT CENTER**  
Jl. Raya Kemang-Parung No. 168A, Kel,  
Kemang  
Kabupaten Bogor, Jawa Barat

**PT.DAYA KOBELCO CMI**  
Kawasan MM2100 Jl.Halmahera Blok  
DD-10  
Cikarang Barat

**KOBELCO USED SK200-10**



**MODEL:** SK200-10 HD  
**CAPACITY:** 20 T (Year 2019)  
**S/NO:** YN15426034  
**ENGINE HRS:** 13056  
**CONDITION:** As Is Condition  
**DELIVERY TERM:** Franco PT. DKCMI, USED EQUIPMENT CENTER, Bogor  
**PRICE:** Rp 799,000,000 (exclude Tax 11%)

**Used crawler crane condition**

**Inspection summary**

| Part          | Evaluation    |
|---------------|---------------|
| LOWER MACHINE | 2.0 ★ ★ ☆ ☆ ☆ |
| OPERATOR CAB  | 3.0 ★ ★ ★ ☆ ☆ |
| PERFORMANCE   | 4.0 ★ ★ ★ ★ ☆ |
| UPPER MACHINE | 4.5 ★ ★ ★ ★ ☆ |
| ATTACHMENT    | 2.0 ★ ★ ☆ ☆ ☆ |
| Total         | 3.0 ★ ★ ★ ☆ ☆ |

**Judgement Criteria**

★★★★★ :Close to brand new or excellent condition.  
★★★★ :Fair Workable condition under operating hrs/mileage serviced.  
★★★ :Workable condition, but minor repair is required. / Small leakage.  
★★ :Workable condition, but mager repair is required. / Middle leakage.  
★ : Non -workable, missing part. / Big leakage.



**MODEL :** SK200-10  
**Y.O.M.:** 2019  
**S/N :** YN15426034

**Conclusion & Comments**

**Conclusion & Comments**

Overall, condition unit ready to work, the performance is in manufacture standard but must be repair for undercariage and attachment

**Conducted the machine  
rectification**

As Is Condition

~Remarks~

•This document reflects the condition of this Excavator at the time of inspection to the best of our ability.  
•We will not be held accountable for any liabilities, from this machine condition report. •Please contact us for the viewing and inspection arrangement of the machine.

**Photos**

