



**USED EQUIPMENT CENTER**

Kawasan Pergudangan Kamal  
Indah I Blok F No.89

Jl.Kamal Benda Raya Jakarta

**PT.DAYA KOBELCO CMI**

Kawasan MM2100 Jl.Halmahera  
Blok DD-10

Cikarang Barat

BULLETIN NO:

**KOBELCO USED SK200-10**



**MODEL:** Kobelco SK200-10  
**CAPACITY:** 20 T (Year 2019)  
**S/NO:** YN15426034  
**ENGINE HRS:** 13056  
**CONDITION:** As Is Condition  
**DELIVERY TERM:** FOT KAMAL  
**PRICE:** Rp 885,000,000 (exclude Tax 11%)

**Used crawler crane condition**

**Inspection summary**

| Part          | Evaluation       |
|---------------|------------------|
| LOWER MACHINE | 2.0 ★★☆☆☆        |
| OPERATOR CAB  | 3.0 ★★★☆☆        |
| PERFORMANCE   | 4.0 ★★★★★        |
| UPPER MACHINE | 4.5 ★★★★★        |
| ATTACHMENT    | 2.0 ★★☆☆☆        |
| <b>Total</b>  | <b>3.0 ★★★☆☆</b> |

**Judgement Criteria**

- ★★★★★ :Close to brand new or excellent condition.
- ★★★★ :Fair Workable condition under operating hrs/mileage serviced.
- ★★★ :Workable condition, but minor repair is required. / Small leakage.
- ★★ :Workable condition, but mager repair is required. / Middle leakage.
- ★ : Non -workable, missing part. / Big leakage.



**MODEL :** SK200-10  
**Y.O.M.:** 2019  
**S/N :** YN15426034

**Conclusion & Comments**

**Conclusion & Comments**

Overall, condition unit ready to work, the performance is in manufacture standard but must be repair for undercariage and attachment

**Conducted the machine rectification**

As Is Condition

~Remarks~

·This document reflects the condition of this Excavator at the time of inspection to the best of our ability.  
 ·We will not be held accountable for any liabilities, from this machine condition report. ·Please contact us for the viewing and inspection arrangement of the machine.

**Photos**

