



**USED EQUIPMENT CENTER**

Kawasan Pergudangan Kamal  
Indah I Blok F No.89

Jl.Kamal Benda Raya Jakarta

**PT.DAYA KOBELCO CMI**

Kawasan MM2100 Jl.Halmahera  
Blok DD-10

Cikarang Barat

BULLETIN NO:

**KOBELCO USED SK200-10**



<b>MODEL:</b>	Kobelco SK200-10
<b>CAPACITY:</b>	20 T (Year 2019)
<b>S/NO:</b>	YN15426053
<b>ENGINE HRS:</b>	15064
<b>CONDITION:</b>	As Is Condition
<b>DELIVERY TERM:</b>	FOT KAMAL
<b>PRICE:</b>	Rp 875,000,000 (exclude Tax 11%)

**Used crawler crane condition**

**Inspection summary**

Part	Evaluation
LOWER MACHINE	2.0 ★ ★ ☆ ☆ ☆ ☆
OPERATOR CAB	3.0 ★ ★ ★ ☆ ☆ ☆
PERFORMANCE	4.0 ★ ★ ★ ★ ☆ ☆
UPPER MACHINE	4.5 ★ ★ ★ ★ ☆ ☆
ATTACHMENT	2.0 ★ ★ ☆ ☆ ☆ ☆
<b>Total</b>	<b>3.0</b> ★ ★ ★ ☆ ☆ ☆



MODEL : SK200-10  
Y.O.M.: 2019  
S/N : YN15426053

**Judgement Criteria**

- ★★★★★ : Close to brand new or excellent condition.
- ★★★★ : Fair Workable condition under operating hrs/mileage serviced.
- ★★★ : Workable condition, but minor repair is required. / Small leakage.
- ★★ : Workable condition, but mager repair is required. / Middle leakage.
- ★ : Non -workable, missing part. / Big leakage.

**Conclusion & Comments**

**Conclusion & Comments**

Overall, condition unit ready to work, the performance is in manufacture standard but must be repair for undercariage and attachment

**Conducted the machine rectification**

As Is Condition

~Remarks~

- This document reflects the condition of this Excavator at the time of inspection to the best of our ability.
- We will not be held accountable for any liabilities, from this machine condition report. ·Please contact us for the viewing and inspection arrangement of the machine.

**Photos**

