

**USED EQUIPMENT CENTER** JI. Raya Kemang-Parung No. 168A, Kel, Kemang Kabupaten Bogor, Jawa Barat

PT.DAYA KOBELCO CMI Kawasan MM2100 Ji.Halmahera Blok DD-10 Cikarang Barat

# KOBELCO USED SK200-10



SK200-10 HD MODEL: CAPACITY: 20 T (Year 2019) S/NO: YN15426053 **ENGINE HRS:** 15062

CONDITION: As Is Condition

Franco PT. DKCMI, USED EQUIPMENT CENTER, Bogor **DELIVERY TERM:** PRICE: 799,000,000 (exclude Tax 11%)

## Used crawler crane condition

#### Inspection summary

Part	Evaluation	
LOWER MACHINE	2.0 🛊 🛊 🌣 🕏	Ž
OPERATOR CAB	3.0 🚓 🌧 🕏 🕏	<u>~</u>
PERPORMANCE	4.0 🕏 🕏 🕏	~
UPPER MACHINE	4.5 衰 衰 衰 🕏	À
ATTACHMENT	2.0 🚖 🚖 🏂 🏂	À
Total	3.0 🍁 🍁 💠	~

Judgement Criteria :Close to brand new or excellent condition

 $\bigstar \bigstar \bigstar \bigstar \qquad \text{:Fair Workable condition under operating hrs/mileage serviced}.$ 

- \*\*\* :Workable condition, but minor repair is required. / Small leakage.
- \*\* : Workable condition, but mager repair is required. / Middle leakage.
- \* : Non -workable, missing part. / Big leakage.



MODEL: SK200-10 Y.O.M.: 2019 S/N: YN15426053

### **Conclusion & Comments**

## Conclusion & Comments

Overall, condition unit ready to work, the performance is in manufacture standard but must be repair for undercariage and attachment

## Conducted the machine

rectification

As Is Condition

### ~Remarks~

<sup>·</sup>This document reflects the condition of this Excavator at the time of inspection to the best of our ability.

<sup>·</sup> We will not be held accountable for any liabilities, from this machine condition report. • Please contact us for the viewing and inspection arrangement of the machine.

**Photos** 



















