

USED EQUIPMENT CENTER
JI. Raya Kemang-Parung No. 168A, Kel, Kemang Kabupaten Bogor, Jawa Barat PT.DAYA KOBELCO CMI Kawasan MM2100 JI.Halmahera Blok DD-10 Cikarang Barat

## **KOBELCO USED SK200-10**



 MODEL:
 Kobelco SK200-10

 CAPACITY:
 20 T (Year 2019)

 S/NO:
 YN15426116

 ENCINE LIPS:
 12573

ENGINE HRS: 12573

**CONDITION**: As Is Condition

DELIVERY TERM:Franco PT. DKCMI, USED EQUIPMENT CENTER, BogorPRICE:Rp799,000,000 (exclude Tax 11%)

# Used crawler crane condition

#### Inspection summary

Part	Evaluation					
LOWER MACHINE	2.0	X	X	纮	23	公
OPERATOR CAB	3.0	X	X	X	22	公
PERPORMANCE	4.0	*	*	A	A	2
UPPER MACHINE	4.5	2	T	2	X	经
ATTACHMENT	2.0	25	The	2	23	公
Total	3.0	*	*	*	25	23

## Judgement Criteria

\*\*\*\* :Close to brand new or excellent condition

 $\bigstar \bigstar \bigstar \qquad \text{:Fair Workable condition under operating hrs/mileage serviced}.$ 

- \*\*\* :Workable condition, but minor repair is required. / Small leakage.

  \*\* :Workable condition, but mager repair is required. / Middle leakage.
- $\bigstar\,$  : Non -workable, missing part. / Big leakage.

# OBELLO

MODEL : SK200-10 Y.O.M.: 2019 S/N : YN15426116

### Conclusion & Comments

# Conclusion & Comments

Overall, condition unit ready to work, the performance is in manufacture standard but must be repair for undercariage and attachment

### Conducted the machine

rectification As Is Condition

### ~Remarks~

<sup>·</sup>This document reflects the condition of this Excavator at the time of inspection to the best of our ability.

<sup>•</sup>We will not be held accountable for any liabilities, from this machine condition report. •Please contact us for the viewing and inspection arrangement of the machine.

<u>Photos</u>



















